

# **SWEENEY** Torque Chart

TC-RSL14-695

# RSL14

PSI	TORQUE OUT FT LBS	PSI	TORQUE OUT FT LBS
1000	961	6000	6624
1200	1188	6200	6850
1400	1414	6400	7077
1600	1641	6600	7303
1800	1867	6800	7530
2000	2094	7000	7756
2200	2320	7200	7983
2400	2547	7400	8209
2600	2773	7600	8436
2800	3000	7800	8662
3000	3226	8000	8889
3200	3453	8200	9115
3400	3679	8400	9342
3600	3906	8600	9568
3800	4132	8800	9795
4000	4359	9000	10021
4200	4585	9200	10248
4400	4812	9400	10474
4600	5038	9600	10701
4800	5265	9800	10927
5000	5491	10000	11154
5200	5718		
5400	5944		
5600	6171		
5800	6397		

